



American Certification Body  
6731 Whittier Avenue Suite C110  
McLean, VA 22101  
USA

Date: 9/21/2019

Ref: Application for Original Equipment Authorization for FCC ID: B94-HNC04PDGP2

Dear Examiner,     The product bearing the FCC ID/TCs in question have not been marketed or sold anywhere in the United States nor anywhere in the world.

This is to request to dismiss grants issued under FCC ID: B94-HNC04PDGP2.

This FCC ID was in error and will be superceded by FCC ID: B94HNC04PDGP2. The error was a typo that inserted a (-) into the ID by mistake. All other documents are correct.

TC Numbers are as follows: TC413183, TC897944, TC135156, TC752082 and TC474636.

Sincerely,

A handwritten signature in black ink that reads "Steven C. Hackett".

Steven C. Hackett

Sr Regulatory Engineer, Intel Corporation acting as agent on behalf of HP Inc. 1501  
Page Mill Road Palo Alto, CA 94304