



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

To whom it may concern:

This device with FCC ID: **B94HNI57CPS** integrates a WWAN module:


	FCC ID	Grant Date
LTE Module	ZMOFM101GL	12/23/2021 for CBE 12/24/2021 for PCB

No hardware design changes are made on the modules, and the software has not been changed to increase the RF output power of the modules. Pursuant to KDB 996369 D02v01, the original modular report as following are submitted to represent the compliance of Part 22/24/27/90/96 conducted RF testing items of this device.

Report Number		
2110RSU029-U1	2110RSU029-U2	2110RSU029-U3
2110RSU029-U4	2110RSU029-U5	2110RSU029-U6

The radiated RF testing items are tested on this host device, and the test report is submitted additionally.

Sincerely,


Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T +886-2-37892469