

8000 Foothills Blvd.  
Roseville, CA 95747  
USA  
Tel: 916-785-3134  
Fax: 916-785-5725  
www.procurve.com



Federal Communications Commission  
7435 Oakland Mills Road  
Columbia MD 21046


**CC:** Compliance Certification Services – Certification Division

**Subject:** Requesting Class II permissive change for FCC ID: B94RSVLC-0505

To Whom It May Concern:

The purpose of this letter is to request a Class II Permissive change for FCC ID: B94RSVLC-0505. The change consists of disabling the channels in 5260-5320 MHz band in the factory. The end user cannot re-activate these channels. This is a software change only. There were no changes made to the hardware to disable operation on these bands. No other changes to the product have been made.

Sincerely,

  
Kenneth Klingler, Sr. Regulatory Engineer  
Hewlett-Packard Company  
April 30, 2007

