

## 8. SETUP PHOTOS

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




Page 94 of 106


#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




Page 95 of 106



Page 96 of 106




Page 97 of 106



Page 98 of 106

#### DIGITAL DEVICE RADIATED EMISSIONS SETUP (USB 1.1)




Page 99 of 106




Page 100 of 106

#### DIGITAL DEVICE RADIATED EMISSIONS SETUP (USB 2.0)




Page 101 of 106



Page 102 of 106

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP (USB 1.1)



Page 103 of 106



Page 104 of 106

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP (USB 2.0)



Page 105 of 106



# **END OF REPORT**

Page 106 of 106