


Test setup – Radiated measurements with USB 1.1



Test setup – Radiated measurements with USB 2.0



Test setup conducted measurements



Test setup AC line conduction.