



FCC ID: B94SLM3065FW

Label & Label Location

HP Inc. 11311 Chinden Blvd. Boise, ID 83714, USA  Product No. :XXXXXX Place : M264 USOC Jack Type:RJ11C	Model: Xpress M3065FW Volts:AC 110-127 V Hertz:50/60 Hz Amps: 5.7 A Ringer Equivalence:0.0B Manufactured:SEPTEMBER 2017  LISTED	FCC ID : B94SLM3065FW Contains FCC ID : B94SPWB4319S This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: i) This device may not cause harmful interference, and ii) This device must accept any interference received, including interference that may cause undesired operation. Complies with Part 68, FCC Rules. US : 6DNFA00BSLM3065FW CAN ICES-3 (B)/NMB-3(B) This product complies with 21 CFR Chapter 1, subchapter J. Contains IC : 466I-SPWB4319S IC : 466I-SLM3065FW
M/C : SL-M3065FW/XAA  S/N : WWWWWWWWWWWW	SSN : Z88KBJAD70001YW	MADE IN CHINA Fabriqu� en Chine

Label



Label Location