

Reply:

From: M. Flom Associates, Inc. [general@mflom.com]
Sent: Thursday, September 25, 2003 4:59 PM
To: Gretchen
Subject: Re: RF NEULINK - FCC ID: B95-NL6000 Job #1297UC3

Attached please find the signed project letter.

The modulation available in this modem for running random data can only be obtained in the diagnostic mode. For the narrow band it is 12 kps (for 9.6 kps requirement) and 22.05 kps (for 19.2 kps). There is no PAM signal feeding the transmitter to deliver a 4-FSK output signal.

- 1) Hence under Rule 2.201, emission designator F1D applies.
- 2) Occupied Bandwidth plots on pages 21-23 and 35-37 are for 12.5 kHz spacing (12 kps); plots on pages 24, 29, 30, 44, and 49 are for 25 kHz spacing (22.05 kps).
- 3) Attached please find the Amended Test Report which includes the Transient Frequency Response test and results.
- 4) R.F. Exposure Safety Instructions: The device comes equipped with time-out timer to avoid damage. The 50% duty cycle statement is to caution the user. See the Instructions to Users and Installers at the end of the MPE Report.
- 5) User Manual: The statement you refer to us a repeat of the other warnings in the manual to again caution the user.
- 6) User Manual, R.F. Exposure: The test for R.F. Exposure was conducted at 20 cm as noted on page 7 in the MPE Report. 'General Population' requirements would imply that the transmitter met the SAR limits. Isn't that so?

We trust the above meets the requirements.

Regards,
Mort Flom, P. Eng., President
mf/cva
M. Flom Associates, Inc.

Confidential - The information in this message is only intended for the person(s) or organization(s) to whom it is addressed. If you are not that person, please contact the sender, and destroy this copy.

TIMCO ENGINEERING INC.

849 NW State Road 45
Newberry, Florida 32669
<http://www.timcoengr.com>
888.472.2424 F 352.472.2030 email: tei@timcoengr.com

September 18, 2003

MR. MORTON FLOM
M. FLOM ASSOCIATES, INC
480-926-3100 480-926-3598
GENERAL@MFLOM.COM

SUBJECT: RF NEULINK - FCC ID: B95-NL6000

REFERENCE: JOB 1297UC3

Dear Mort,

Questions:

1. Necessary Bandwidth Calculation: Please explain how this number is derived from the Pulse Amplitude Modulated (PAM) signal feeding the transmitter that delivers a 4-FSK output signal. The emission designator is marked as F1D.
2. Occupied Bandwidth Plots: Is the plot marked "random data" running at maximum data rate? Part 90.203(j) states: "...the equipment must be capable of supporting a minimum data rate of 4800 bits per second per 6.25 kHz of channel bandwidth." Please verify and state the EUT complies with this requirement for the 12.5 and 25 KHz bandwidths.
3. Transient Frequency Response: Part 90.214 calls for Transient Frequency Response Plots. Please submit. (none were found)
4. User Manual: RF Exposure Safety Instructions: For what reason is the 50% duty cycle statement listed?
5. User Manual: RF Exposure Safety Instructions: The statement "RF Exposure compliance must be addressed at the time of installation." Does this statement apply when it is stated to maintain a 20cm separation distance from the antenna?
6. User Manual: RF Exposure Safety Instructions: In the section called "Warning" it states: "...the requirements of Occupational/Controlled Exposure Environment, etc...." This EUT meets the "General Population" requirements, as it should. Should this statement be changed to "General Population," etc?

Sincerely,

Gretchen Torres

