

DENSO TEN

2-28, Goshō-dori 1-chōme,
Hyōgo-ku, Kobe, 652-8510 Japan
Tel.: +81.78-682-2159
Fax.: +81.78-671-7160

FCC Request for Rule Changes based on 17-93

February 22, 2021

Federal Communication Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, Maryland 21046

FCC ID : BABFT0091A
Applicant : DENSO TEN Limited

To Whom It May Concern:

This request is to add Equipment Code CXX for FCC ID: BABFT0091A, originally granted on 11/09/2016. We change FM receiver part had confirmed conformity of Part 15 Subpart B to "Certification" procedure from "Verification" based on KDB 178919 D02 Q&A7.

This Car Navigation with 2.4 GHz band WLAN/ 5 GHz band WLAN/ Bluetooth was granted as Part 15 Subpart C and Part 15 Subpart E for composite "DTS"/ "DSS"/ "NII", and we add "CXX - Communications Rcvr for use w/ licensed Tx and CBs" as Equipment Code to this product.

This time, we performed the re-testing of Part 15 Subpart B because we change the following points from the based model. Please refer to the test report submitted with this application.

- Change of SRC IC and pattern
- Change of gyro sensor IC and pattern.
- Removal of VTR circuit

Thank you for your attention to this matter.

Sincerely,

Kaoru Abe

Kaoru Abe
Department General Manager
Quality Assurance Group Quality Control Div
Regulatory Management Dept.
DENSO TEN Limited