

**Request for Class II Permissive Change**

May 22, 2024

UL Verification Services Inc.  
47173 Benicia Street, Fremont, CA 94538FCC ID : BABTN0022A  
Applicant : DENSO TEN Limited

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: BABTN0022A granted on 10/29/2021.  
We changed the following points from the original model.

- Exterior Design
- Addition of Indicator Board
- SW PCB Change
- CPU PCB Change (GPS improvement)
- Antenna cable


We submit the following documents related to this change. There is no change before and after change except for these documents.

<input checked="" type="checkbox"/>	Test Report
<input checked="" type="checkbox"/>	RF Exposure
<input checked="" type="checkbox"/>	External Photo
<input checked="" type="checkbox"/>	Internal Photo
<input type="checkbox"/>	User Manual
<input type="checkbox"/>	Label Drawing/ Location
<input type="checkbox"/>	Block Diagram
<input checked="" type="checkbox"/>	Theory of Operation
<input checked="" type="checkbox"/>	Schematic Diagram
<input type="checkbox"/>	Parts List
<input type="checkbox"/>	Tune up Info.

This time, we performed the testing and confirmed that this product still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely,



---

Kaoru Abe  
Department General Manager  
Quality Assurance Group Quality Planning Div  
Regulatory Management Dept.  
DENSO TEN Limited