

**RICOH**

810 Shimoimaizumi, Ebina-city,  
Kanagawa 243-0460 Japan

May 16, 2008

**Federal Communication Commission  
Equipment Authorization Division  
Application Processing Branch  
7435 Oakland Mills Road  
Columbia, Maryland 21046**

Subject : Reassessment under Section 2.1043 of FCC Part 2  
(Class II Permissive Change)  
Company : Ricoh Company Ltd.  
Product : Full Color MFP (Aficio MP C4500, Aficio MP C3500)  
FCC ID : BBP-RFAPL01

This is request on reassessment of the granted product (FCC ID: BBP-RFAPL01) on April 20, 2006. We request the expansion of the followings.

1. To add the grant note that the additional measurement to verify co-location operation is performed. (Please see the attached test report)

The difference between the certified product and the modified one is the above only.

The device co-located with Full Color MFP (FCC ID: BBP-RFAPL01) is already approved Bluetooth Compact Flash Card (FCC ID: NXXBL-631).

Only one optional interface board can be installed in the Full Color MFP at a time.

Therefore, the Bluetooth Compact Flash Card cannot be installed concurrently with another optional wireless interface.

Since this Bluetooth Compact Flash Card is optional, all the necessary FCC regulatory statements for wireless device are included in users manual of Bluetooth Compact Flash Card itself for users. Also, FCC ID label is visible before users install the unit to Full Color MFP.



---

Seiji Nakamura

Leader

EMC and Telecommunication Group Products Safety Engineering Center