

APPENDIX 3: Photographs of test setup

Conducted emission



UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400


Facsimile : +81 463 50 6401

Radiated emission


Front view



Rear view (below 1GHz)



Rear view (above 1GHz)



UL Japan, Inc.







Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401

Pre-check of the worst position

Antenna	Module
<p data-bbox="459 353 539 387">X-axis</p> 	<p data-bbox="1098 353 1177 387">X-axis</p> 
<p data-bbox="459 873 539 907">Y-axis</p> 	<p data-bbox="1098 873 1177 907">Y-axis</p> 
<p data-bbox="459 1393 539 1426">Z-axis</p> 	<p data-bbox="1098 1393 1177 1426">Z-axis</p> 

END OF REPORT

UL Japan, Inc.

Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401