



Compliance Certification Services

GLOBAL TEST & CERTIFICATION
FCC, IC, CE, NCC, IDA, VCCI, BSMI, MIC
SAR/HAC, DFS, CTIA, UL/CUL, TUV, CSA
NVLAP ACCREDITATION TCB / CAB

47173 BENICIA STREET, FREMONT CA 94538
TEL: (510) 771-1000 FAX: (510) 661-0888
WWW.CCSEMC.COM

Date: Aug. 29, 2007

Federal Communications Commission
Equipment Authorization branch
7435 Oakland Mills Road
Columbia, MD 21046

Re: Revised test report for CASIO COMPUTER CO., LTD.,
FCC ID: BBQIT3000

Gentlemen:

We request to replace the test report for CASIO COMPUTER CO., LTD., FCC ID:
BBQIT3000.

Please see reason below:

During the class II permissive change filing, we found that the original grant only listed the eirp output power.

Based on FCC requirement, all TCBS have to list the peak RF conducted output power for all 15.247 device and all 15.247 devices are subject to none co-located restrictions.

Thus, by communicating with Casio, we performed RF conducted output power and incorporated it into the revised class II permissive change report.

Please kindly supersede the original test report and accept revised test report(07J11169-10E FCC DTS BLUETOOTH Report)for this application.

Thanks,

Claire Hoque

Claire Hoque
Compliance Certification Services
47173 Benicia Street
Fremont, CA 94538, USA