


GBD-H2000_CW3515 Display of certificate number

1. Hold down S2 for about 2 seconds will changes to setting mode and "SETTING" is displayed.
※ Press S2 to "REGULATORY" once. / Press S3 to "REGULATORY" by 3 times.
2. Press S5 and select "REGULATORY" by S2 or S3.
※ Press S2 to "REGULATORY" once. / Press S3 to "REGULATORY" by 3 times.
3. Press S5, the certificate number will be displayed. The screen changes with S2 or S3.
※ Press S1 to return to the previous screen.



① Instructions for Label display are provided in the user manual for the entire product.

② This device does not require special accessories or supplemental plug-ins to access the information"

