


# DW-H5600\_CW3516 Display of certificate number



1. Hold down S2 for about 2 seconds will changes to setting mode and “SETTING” is displayed.

2. Press S2 and select "REGULATORY" by S3.

※ Press S3 to "REGULATORY" by 3 times.

3. Press S2, the certificate number will be displayed. The screen changes with S2 or S3.

※Press S1 to return to the previous screen.