

8


7

6

5

4

3



Align pad print around centre of item

Use CE mark as reference, to ensure right dimensions

Use KCC mark as reference, to ensure right dimensions

Use layout file as input for pad print

2

**CONFIDENTIALITY NOTICE:**

This document is the property of GN A/S and must be treated as confidential. The document must not be used, or disclosed to any third party, without written permission of GN A/S. Copyright © 2007 GN A/S. All rights reserved.

Process control dimensions are marked:

IQC/OQC Characteristics for Evaluation:

# 1

Date of Change:

Description of Change:

Responsible:

1



Matr. Spec: (See B.O.M.)

Matr. type:

3D file name:

Cosmetic Standard: GSC.ST.00002

Part Marking.: GSC.PR.00102

Issued by:

JJO

Issued:

13.12.2012

Drawing Scale:

2:1

Size:

A4

Approved by:

Date Approved:

Projection:



Description:

Pad Print Placement, HS, Copenhagen

Document No:

50-06162

Doc. Revision:

D

Units:

mm

Page No:

1 of 1

A

B

C

D

E

F