
#### **SETUP PHOTOS** 10.

#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







#### **RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)**








#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION














## POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

#### **EUT POWERED BY AC/DC ADAPTER VIA USB CABLE**





# **END OF REPORT**

Page 85 of 85