
SETUP PHOTOS 10.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)





RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION













POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

EUT POWERED BY AC/DC ADAPTER VIA USB CABLE





END OF REPORT

Page 84 of 84