
10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP




Page 152 of 155




RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




Page 153 of 155






TEL: (510) 771-1000 FAX: (510) 661-0888

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 155 of 155