

## 11. SETUP PHOTOS


#### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Page 50 of 53




### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)



Page 51 of 53





### RADIATED RF MEASUREMENT SETUP



UL Verification Services FORM NO: CCSUP4701D 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services.

Page 52 of 53





# **END OF REPORT**

Page 53 of 53