

10. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







UL Verification Services FORM NO: CCSUP4701D 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services.


Page 29 of 31

RADIATED RF MEASUREMENT SETUP





Page 30 of 31



END OF REPORT

UL Verification Services FORM NO: CCSUP4701D 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services.

Page 31 of 31