
SETUP PHOTOS 10.

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION
















POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP


EUT POWERED BY AC/DC ADAPTER VIA USB CABLE





EUT POWERED BY HOST PC VIA USB CABLE





END OF REPORT

Page 92 of 92