

V9720CMZ(TADM-H202F / TCMN0682PA20C4)

1.Front of EUT




2.Rear of EUT



3. Bottom of EUT



4. FCC requirement of rear side.




V9720CMZ(TADM-H202F / TCMN0682PA20C4)



1.Inner of EUT




2.Main Board





3. Power Board





5. LGIT Tuner(HADM-H202F)





6.Inner of LGIT Tuner



7. Samsung Tuner(TCMN0682PA20C4)



8.Inner of Samsung Tuner



- Manufactured under license from Dolby Laboratories. "Dolby" and the double-D symbol are trademarks of Dolby Laboratories.
- APPARATUS CLAIMS OF U.S. PATENT NOS. 4,631,603, 4,577,216, 4,819,098, AND 4,907,093 LICENSED FOR LIMITED VIEWING USES ONLY.
- "DTS" and "DTS Digital Out" are trademarks of Digital Theater Systems, Inc.
- THIS PRODUCT COMPLIES WITH APPLICABLE REQUIREMENT OF THE DHHS PERFORMANCE STANDARD FOR LASER PRODUCTS, 21 CFR SUBCHAPTER J. DHHS CODE : GI
- THIS CLASS B DIGITAL APPARATUS COMPLIES WITH CANADIAN ICES-003. CET APPAREIL NUMERIQUE DE LA CLASSE B EST CONFORME A LA NORME NMB-003 DU CANADA.
- THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.

	CAUTION RISK OF ELECTRIC SHOCK DO NOT OPEN	
AVIS	RISQUE DE CHOC ELECTRIQUE NE PAS OUVRIR	
 		
DVD PLAYER / VIDEO CASSETTE RECORDER MODEL NO. V9720CMZ AC120V ~ 60Hz 16W SERV. NO. V9720CMZ		
 		
FCC ID: BEI9QKE40460 MADE IN INDONESIA Marketed and Distributed by LG Electronics U.S.A., Inc. 1000 Sylvan Avenue, Englewood Cliffs, NJ		
Supplementary Television Broadcasting Receiving Apparatus, Appareils supplémentaires de réception de télévision, Canada. U.S. PATENTS 4,002,986; 4,317,227; 4,516,170; 4,598,425, LICENSED UNDER CANADIAN PATENTS 1,120,582; 1,146,032.		
P/N 3850R-Z0000		