






Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11n-HT40	Tested By	Brian Hsieh
Frequency	TX 2452MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11n-HT40	Tested By	Brian Hsieh
Frequency	TX 2462MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE20	Tested By	Brian Hsieh
Frequency	TX 2412MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE20	Tested By	Brian Hsieh
Frequency	TX 2442MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE20	Tested By	Brian Hsieh
Frequency	TX 2462MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE20	Tested By	Brian Hsieh
Frequency	TX 2472MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
 Fax: +886 2 26099303





Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE40	Tested By	Brian Hsieh
Frequency	TX 2422MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE40	Tested By	Brian Hsieh
Frequency	TX 2442MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE40	Tested By	Brian Hsieh
Frequency	TX 2452MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB




Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE40	Tested By	Brian Hsieh
Frequency	TX 2462MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			3dB



Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE20	Tested By	Brian Hsieh
Simultaneous Factor	10 log(n) (Note: "n" is antenna number)		3dB








Test Date	2020/11/03	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	802.11ax-HE40	Tested By	Brian Hsieh
Simultaneous Factor	10 log(n) (Note: "n" is antenna number)		3dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	BLE	Tested By	Brian Hsieh
Frequency	TX 2402MHz		
Simultaneous Factor10 log(n) (Note: "n" is antenna number)			0dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	BLE	Tested By	Brian Hsieh
Frequency	TX 2440MHz		
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0dB



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

Test Date	2020/09/29	Temp./Hum.	24°C/52%
Cable Loss	0.60dB	Test Voltage	AC 120V, 60Hz (via AC Adapter)
Mode	BLE	Tested By	Brian Hsieh
Frequency	TX 2480MHz		
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0dB

