



**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3






Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5200MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**




**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2018/10/27	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	I
		Frequency	TX 5240MHz
Cable Loss	2.92dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3






**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5260MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**






**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5300MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**



**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan


**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3




**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**




Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5500MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303




**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**


Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5580MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3









Test Date	2018/10/30	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3






Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	II-2C
		Frequency	TX 5720MHz
Cable Loss	3.37dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3








**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**




Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5745MHz
Cable Loss	3.91dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3






Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	3.91dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3



Audix Technology Corp.  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City 244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303





Test Date	2018/10/31	Temp./Hum.	25°C/55%
Mode	802.11n-HT20	UNII Band	III
		Frequency	TX 5825MHz
Cable Loss	3.91dB	Test Voltage	AC 120V, 60Hz (Via AC Adapter)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3

