



● Occupied (99%) Bandwidth













802.11n-HT20

AUX









Main



802.11n-HT40


AUX

Main










802.11ax-HE20

AUX




Main










802.11ax-HE40

AUX




Main



Audix Technology Corp.
No. 491, Zhongfu Rd., Linkou Dist.,
New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303




Audix Technology Corp.


No. 491, Zhongfu Rd., Linkou Dist.,


New Taipei City 244, Taiwan

Tel: +886 2 26099301

Fax: +886 2 26099303








BLE

PHY Coded S2



PHY Coded S8

