



### 802.11b-SISO A




Date: 17.AUG.2023 12:07:15

### 802.11g-SISO A




Date: 17.AUG.2023 12:08:55

### 802.11ax-20 MHz -SISO A




Date: 11.OCT.2023 01:43:30

### 802.11ax-40 MHz -SISO A




Date: 11.OCT.2023 02:24:33

### 802.11ax-20 MHz (Partial RU)-SISO A




Date: 12.OCT.2023 20:04:09

### 802.11ax-40 MHz (Partial RU)-SISO A




Date: 12.OCT.2023 20:12:46

### 802.11b-SISO B




Date: 11.OCT.2023 21:29:32

### 802.11g-SISO B




Date: 11.OCT.2023 21:30:38

### 802.11ax-20 MHz-SISO B




Date: 11.OCT.2023 21:32:13

### 802.11ax-40 MHz-SISO B




Date: 11.OCT.2023 21:35:30

### 802.11ax-20 MHz (Partial RU 26/0)-SISO B




Date: 12.OCT.2023 20:18:20

### 802.11ax-40 MHz (Partial RU 242/61)-SISO B




Date: 12.OCT.2023 20:18:48

### 802.11ax-20 MHz-MIMO




Date: 17.AUG.2023 12:21:14

### 802.11ax-40 MHz-MIMO




Date: 17.AUG.2023 12:22:08

### 802.11ax-20 MHz (Partial RU)-MIMO



Date: 13.SEP.2023 16:26:50

### 802.11ax-40 MHz (Partial RU)-MIMO



Date: 13.SEP.2023 16:25:09