


## A.5 EMISSION LIMITATIONS

Test Date	2023/10/16 ~ 31	Temp./Hum.	24 ~ 25°C/53 ~ 69%
Cable Loss	WiFi: 1.10dB, BLE: 1.10dB	Tested By	Harry Huang
Test Voltage	AC 120V, 60Hz (via AC Adapter)		




File Number: C1M2310117

Report Number: EM-F230543




APPENDIX A-Page 231 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303



Report Number: EM-F230543



APPENDIX A-Page 232 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 233 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 234 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




## File Number: C1M2310117

Report Number: EM-F230543




APPENDIX A-Page 235 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303



Report Number: EM-F230543



APPENDIX A-Page 236 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 237 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 238 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543




APPENDIX A-Page 239 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303



Report Number: EM-F230543



APPENDIX A-Page 240 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 241 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 242 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543




APPENDIX A-Page 243 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303



Report Number: EM-F230543



APPENDIX A-Page 244 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303




File Number: C1M2310117

Report Number: EM-F230543



APPENDIX A-Page 245 of 275 Tel: +886 2 26099301 Fax: +886 2 26099303



Report Number: EM-F230543