



1953 Concourse Drive  
San Jose, CA 95131

To whom it may concern:

5-2-2005

The input voltage will be revised to 115VAC +/- 10% in the Model 5290 User's Guide.

Regards,  
Edmund Fong  
Executive Vice President