

**Barry Quinlan**

---

**From:** "Ruby Dulmage" <ruby.dulmage@nemkona.com>  
**To:** "Curtis-Straus TCB" <certification@curtis-straus.com>  
**Sent:** Monday, September 30, 2002 1:17 PM  
**Attach:** SL-6440-41PCBrear.pdf; SL-6440-41PCBfront.pdf  
**Subject:** Re: DESA FCC ID: BJ4-64WDB40TX

Hi Barry:

1. Attached are the interior photos.
2. Yes, fresh batteries were used for testing.

Thanks,  
Ruby

Ruby Dulmage  
Submissions Specialist  
Nemko Canada Inc.  
303 River Road, R.R. 5  
Ottawa, ON K1V 1H2  
Tel: 613-737-9680 ext 232  
Fax: 613-737-9691  
Email: [ruby.dulmage@nemkona.com](mailto:ruby.dulmage@nemkona.com)

----- Original Message -----

**From:** [Curtis-Straus TCB](#)  
**To:** [Ruby Dulmage](#)  
**Sent:** Friday, September 27, 2002 5:00 PM  
**Subject:** DESA FCC ID: BJ4-64WDB40TX

Hi Ruby,

We have identified these issues following our review of the application:

1. We do not appear to have any internal photos.
2. Please confirm fresh batteries were used during the testing.

Best regards

Barry C. Quinlan  
Certification Manager  
Curtis-Straus TCB