

Mike Kuo

To: lucy_tsai@ccsemc.com.tw

Subject: RE: 回信 : RE: TATUNG CO., FCC ID: BJM-TTABB12DBG, Assessment NO.: AN05T4834, Notice#1-from Lucy

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]

Sent: Thursday, June 02, 2005 9:12 AM

To: Mike Kuo

Cc: lucy_tsai@ccsemc.com.tw

Subject: TATUNG CO., FCC ID: BJM-TTABB12DBG, Assessment NO.: AN05T4834, Notice#1

Question#1: Page 3 of antenna spec. indicated the PCB antenna gain is 0.9dBi which doesn't agree with 0.38dBi shown on the test report. Please correct.

Ans: Please refer the revised antenna spec. as attachmet.

Question#2: According to the test procedure, the setting of VBW for measuing average bandedge test shall be 10Hz, but page 22 of 802.11b mode's bandedge test at the high channel indicated the setting of VBW is 30Hz. Please re-do the test to demonstrate the compliance.

Ans: The test rpt had been revised, please refer the attachment.

Best Regards,

Lucy

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

6/10/2005