

This letter is written in compliance with 2.925 (2) and (2)e concerning the placement of the nameplate containing the FCC identifier. As shown in the following photograph, the nameplate has been placed on the bottom floor of the transmitter cabinet. This is the preferred location as requested by the end user (the Federal Aviation Administration). The FAA did not want the nameplate on the front or rear door due to the fact that the doors are removable. Placement of the nameplate on the sides of the cabinet was not preferred because there is likely to be other cabinets installed on either side blocking access to the nameplate.

