Unisen Limited

Federal Communications Commission 7345 Oakland Mills Road Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: BOOKP-Y4133821

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by Unisen Limited will establish a new FCC ID under our grantee code for the purpose of marketing.

The original grant to (Unisen Limited with FCC ID: (BOOKP-Y4073821) will remain in effect.

Per 2.933(b)

- 1.) The original identification is: BOOKP-Y4073821
- 2.) The original granted date is: 11/19/2015
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Lable and Location Info

Sincerely

City and Country:	Date:	Name: (this must be a person)		Signature: (or official company stamp)
Hong Kong	2016.11.12	Dengyi	Engineer	Dergji