

# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 71 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 72 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 73 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 74 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 75 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 76 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 77 of 81





# SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 78 of 81



# SRD-Testreport


CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 79 of 81



# SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 80 of 81



# SRD-Testreport

CETECOM ICT Services GmbH Saarbruecken, Germany



Test report No.: 4-1712-01-02b/05

Date: 2005-06-09

Page 81 of 81

