

TO: FCC
ATTN: Mr. Joe Dichoso
FROM: Len Sabato/ Horizon
Subject: BRWXF421EX Manual Addition
Reference # 12093 EA96000

RE) Manual Addition to comply with Section 95.653

We will be adding the following information to page 28 of the instruction manual:

“ The Federal Communications Commission (FCC) requires that changes in radio frequency must be performed by an authorized service technician only (Horizon Service Center).

Any frequency changes made by a non-certified technician may result in a violation of the FCC rules”.

We are hopeful that this warning will be acceptable. If you require any changes in the wording of this addition, please advise.

Best Regards;

Len Sabato