



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

May 1, 2007

RE: FCC ID: BV2-MPGBR052_ATCB004854
Attention: Mr Kazufumi Nakai

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that as this is a WLAN type device operating in the 2412-2462MHz range and not a Frequency Hopping device the equipment code on the 731 should be DTS and not DSS. Please correct.
2. Please complete page 1 of the Annex A rf technical brief form. Please include the calculated or measured MPE of the device.
3. Please explain how the label is permanently affixed to the device.
4. Please note that the device does not appear to have its own power regulation but instead gets regulated power from a PCI bus. This then would be an LMA and not a full modular approval. Please explain how this meets requirement 3 of DA001407. If the device does in fact get regulated power from a PCI bus and does not have its own DC regulated power on the module, please correct the request to be for an LMA. Please also then either provide testing inside a representative host or please provide some form of attestation to show that the DC regulator used in any host of the companies listed in the manual for which the LMA is to be used will have properly regulated power.
5. Please provide a separate MPE report for this device.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.