

EXTERNAL PHOTOS – NUCR-HU




Front view (NUCR-HU)



Rear view (NUCR-HU)


Accessories



Input/output auxiliary relay and switched interface box



USB serial cable




Auxiliary device NIRC4 as power supply to the bus



AC/DC adapter to NIRC4



Bus cable (both DC and RS485)



RFID card