

4/9/2016

HME requested confidentiality for the schematic in the original filing of the Class II Permissive change for the XCVR6K1, however there was failure to communicate that to the FCC. Due to this error, we acknowledge awareness that the schematic was made available to the public for a period of time.

Sincerely,



Karl Knoblock  
Senior Electronics Engineer