



Description of Permissive Change

Date: April 21, 2009

The differences compared with the original design are:

PCB material changed with partial components be replaced by second source
(circuit and function are identical to original)

FCC ID	PCB Material	
	Original	Now
C3K1133	FR4	FR1

If you have any questions regarding this, please don't hesitate to contact us.

Sincerely yours,

Stephen M. Stegner
EMC/Safety Engineer
Microsoft Corporation
TEL:(425) 706-2697
FAX: (425) 936-7329
E-mail: sstegner@microsoft.com