



**May 1, 2015**

**Federal Communications Commission**

Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, Maryland 21046

**LETTER OF ATTESTATION REGARDING THE  
APPLICATION FOR CERTIFICATION OF FCC ID: C3K1657**

To whom it may concern,

Per FCC KDB 848637, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

The device complies with the requirements for software configuration control as discussed in KDB594280. Additionally for the 2.4GHz ISM band, Channels 12 and 13 are inoperable.

Sincerely,

A handwritten signature in black ink, appearing to read "Stephen Stegner".

*Stephen M. Stegner*

**Compliance Engineer  
Microsoft Corporation**