


11. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)












RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION








This report shall not be reproduced except in full, without the written approval of UL LLC.














POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT

Page 126 of 126