

9. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



Page 49 of 53


RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)





Page 50 of 53


RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





Page 51 of 53

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





Page 52 of 53

ORIENTATIONS





END OF REPORT

Page 53 of 53

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.