



Cover Letter for Leveraging DFS conducted test data between Models 1867, 1868 and 1872

Models 1867, 1868, 1872 are electrically and RF equivalent as they share the same motherboard, radio module and on-board radio circuit. The only difference is the antenna and the matching components after the RF port.

DFS conducted testing is performed on model 1868 (FCC ID: C3K1868, IC: 3048A-1868) and the data is leveraged for models 1867 (FCC ID: C3K1867, IC: 3048A-1867) and 1872 (FCC ID: C3K1872, IC: 3048A-1872). The three devices are DFS client devices and use the same radio module with the same set of baseline radio firmware and drivers. Even though the final firmware/driver versions may be different between the three models, this does not affect the response of the client devices to the master device clear channel announcements.

Signed:

A handwritten signature in black ink, appearing to read "Chaitrali Limaye".

Chaitrali Limaye

Compliance Engineer

Microsoft