

# IDENTIFICATION LABEL

<p><b>DAEWOO</b> MICROWAVE OVEN (HOUSEHOLD) MODEL NO.: KOR-1B4H POWER INPUT 120V 60Hz AC ONLY, 1.5KW, SINGLE PHASE WITH GROUNDING.</p> <p><b>FCC ID: C5F7NF1BMO1100</b> MADE IN KOREA</p> <p>DHHS CODE: H7NF DISTRIBUTED BY: DAEWOO ELECTRONICS AMERICA, INC. 120 CHUBB AVENUE LYNDHURST, NEW JERSEY 07071, U. S. A. SERIAL NO.: MANUFACTURED:</p>	<p><b>UL</b> LISTED 55K4</p>	<p><b>CAUTION</b> *THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.</p> <p><b>WARNING</b> *DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH-VOLTAGE POTENTIALS. *TO ENSURE CONTINUED PROTECTION AGAINST SHOCK HAZARD CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. *CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL-DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: FAN MOTOR, LOW VOLTAGE TRANSFORMER (TOUCH CONTROL TYPE), TIMER &amp; TIMER MOUNTING BRACKET (MECHANICAL TYPE). RISK OF ELECTRIC SHOCK. NON REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS</p> <p>*NOT FOR BUILT-IN INSTALLATION</p>
--	----------------------------------	---

**FCC ID: C5F7NF1BMO1100**