


Report File No. : STROR-06-020

Date of Issue : 2006-03-23

Page: 45 of 47

FCC ID: C5FAXI515

Internal View of EUT



Top View of Main-board



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Testing Korea Co., Ltd.

18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371

www.sgstesting.co.kr



Report File No.: STROR-06-020

Date of Issue : 2006-02-10

Page: 46 of 47

FCC ID: C5FAXI515

Bottom View of Main-board



Top View of RF board



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.




Report File No.: STROR-06-020

Date of Issue : 2006-03-23


Page: 47 of 47

FCC ID: C5FAXI515

Top View of RF board(Shielding Removed)



Top View of RF board



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.