






AC I.P. 45-65Hz	FUSE F3
220/240 Vrms 3.5A	T&A 250V IEC
110/120 Vrms 7A	T&A 250V IEC

F1 F20A
32V RMS

22-32 Vrms
DC I.P. 10A



F2
T&A
250V
IEC



F3

CN2 FACILITIES 2



CN4 EXT CLOCK



CN3 APPLIQUE/FILTER INTERFACE



CN5 REMOTE



CN6



DANGER HIGH RF VOLTAGE
Connect antenna before use



W/U
G/RX

RX
UHF

UHF
TX

RX/TX
VHF

EXT
REF