

0 5 10 15cm


REPORT 2374
FCC ID: CASTBA8K2



REPORT 2374
FCC ID: CASTBA8K2




0 5 10 15cm



REPORT 2374
FCC ID: CASTBA8K2



0 5 10 15cm



7-801-20-0000
K1180101871 8V112
K1180101278 8V121
21-1-0028

ASIA
DC-DC CONVERTER
SH12-15S1000
SER.NO. 101161
ASIA ELECTRONICS IND.CO.,LTD.
MADE IN JAPAN

ISOTEMP
RESEARCH, INC.
P/N 539-00010-56
MODEL OCK091-39
FREQ. 10,000 HZ
S/N 2743-137
DATE 0424
FSC 31785


ZAI
220-01580-01
1801-20-0000
MADE IN NEW ZEALAND



0
5
10
15cm

REPORT 2374
FCC ID: CASTBANK






130PCK2 R 001 U 88
100900445 5 2008606
40

8 008 0 30
13 5 2008680

REPORT 2374
FCC ID: CASTBA8K2



0 5 10 15cm



REPORT 2374
FCC ID: CASTBA8K2





0 5 10 15cm

REPORT 2374
FCC ID: CASTBA8K2



0 5 10 15cm






0 5 10 15cm

REPORT 2374

FCC ID: CASTB8K2




0 5 10 15cm
REPORT 2374
FCC ID: CASTBA8K2
ZAI



EP04407
MC 4474
3004
OXAROCKA 9 003
J 102900467 9 20

Handwritten note in yellow marker: 2004 10 20



CAUTION!
LETHAL VOLTAGES
DISCONNECT FROM SUPPLY
BEFORE DISMANTLING.

TSK000AD
RECEIVED FROM THE SUPPLIER
CE NAD6

RELEVA

RELEVA

REPORT 2374
FCC ID: CASTBARK2



0 5 10 15cm

IO/CI

IO/CI



0
5
10
15cm
REPORT 2374
FCC ID: CASTB8K2
ZAI



