


Label details

Sample of label to be used

 SN: 18186046 148-174MHz  
TYPE CODE (M/N): TBCB1X 100902402  
FCC ID: CASTBCB1X T01-01104-DAAA  
IC: 737A-TBCB1X CAN RSS-GEN/CNR-GEN  
19Aug2013       N46  
MADE IN NEW ZEALAND BY TAIT Limited

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC  
RULES. OPERATION IS SUBJECT TO THE FOLLOWING  
TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE  
HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST  
ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING  
INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.

Contains intellectual property licensed by Digital  
Voice Systems Inc., Motorola Inc. and Tait Ltd

Label on receiver module outside of the rack



2 x receiver modules in the rack front view





148-174MHz  
100902402

TYPE CODE (M/N): TBCB1X

FCC ID: CASTBCB1X

IC: 737A-TBCB1X

T01-01104-DAAA

CAN RSS-GEN/CNR-GEN

N46



19Aug2013  
MADE IN NEW ZEALAND BY TAIT Limited

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC  
RULES. OPERATION IS SUBJECT TO THE FOLLOWING  
TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE  
HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST  
ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING  
INTERFERENCE THAT MAY CAUSE UNDESIRABLE OPERATION.

Contains intellectual property licensed by Digital  
Voice Systems Inc., Motorola Inc. and Tait Ltd

VOICE 077

19Aug2013  
MADE IN NEW ZEALAND BY TAIT Limited

148-174MHZ  
100902402  
T01-01104-DAAA  
CAN RSS-GEN/CNR-GEN  
N46



THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION.

Contains intellectual property licensed by Digital Voice Systems Inc., Motorola Inc. and Tait Ltd

2 Receiver modules in the rack rear view



