



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

April 29, 2003

RE: Johnson Controls Interiors L.L.C.

FCC ID: CB2UCONN Permissive Change

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Although the attestation letters state that there have not been any changes to the Bluetooth portion of the device, upon comparing the block diagram in this application to the original, it appears that there may be a change to the baseband of the TX. Additionally it appears that the original contained one Broadcom IC BCM2033, but the new application appears to show a 2 IC Agere Bluetooth Solution, W7020 and W7400 in the block diagram. Please explain as this change of TX chips will not be allowed under a Permissive Change.
- 2) Upon further investigation, the schematic appears to contain the original part IC BCM2033. Please explain as this does not agree with the block diagram.
- 3) Note that only a preliminary review has been performed. Before processing can continue, the above issues must be addressed.

Timothy R. Johnson
Examining Engineer

Direct Phone: 404-414-8071

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.