



FCC ID: CB2WLHL4 Internal Photographs.




Internal Photograph 1: Rear cover removed, showing location of circuit board.




Internal Photograph 2: PCB removed from front housing.

Johnson Controls LLC Electronics Laboratory 915 East 32nd Street, Holland MI 49423 Tel 616-394-6194 Fax 616-394-6100






Internal Photograph 3: Disassembled view, front side of components.




Internal Photograph 4: Front Surface of circuit board.

Johnson Controls LLC Electronics Laboratory 915 East 32nd Street, Holland MI 49423 Tel 616-394-6194 Fax 616-394-6100






Internal Photograph 5: Reverse Surface of printed circuit board.



Internal Photograph 6: Detail view of RF portion of circuit board with the antenna on the right side of photograph.

Johnson Controls LLC Electronics Laboratory 915 East 32nd Street, Holland MI 49423 Tel 616-394-6194 Fax 616-394-6100





Internal Photograph 7: Detail view of RF circuit with shield removed.