

## **Internal Photographs**





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1


Digital Monitoring Products, Inc. Model: 1184 CO Detector


File: IntPho CCKPC0104

Test #:110914C SN: W30CO ENG1 Test to: FCC Parts 2 and 15.249, RSS-210

Page 1 of 3

FCC ID#: CCKPC0104 IC: 5251A-PC0104 Date: October 3, 2011







Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Digital Monitoring Products, Inc. Model: 1184 CO Detector

Test #:110914C SN: W30CO ENG1 Test to: FCC Parts 2 and 15.249, RSS-210

File: IntPho CCKPC0104

FCC ID#: CCKPC0104 IC: 5251A-PC0104 Date: October 3, 2011 Page 2 of 3





Rogers Labs, Inc. 4405 West 259<sup>th</sup> Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1 Digital Monitoring Products, Inc. Model: 1184 CO Detector

Test #:110914C SN: W30CO ENG1 Test to: FCC Parts 2 and 15.249, RSS-210

File: IntPho CCKPC0104

FCC ID#: CCKPC0104 IC: 5251A-PC0104 Date: October 3, 2011 Page 3 of 3